

Project Name	Released By	SW Build Numbers	Release From Test Date
CORIOgrapher	David Reynaga	1.0.4.0	24/10/2014
Release Description			
Software Update			
Formal release - some known issues below			
Previous Release			
1.0.2.0		03/06/2014	
New Features Included In Release			
Frame-lock to a source			
CORIOmaster firmware version checking (will only work with M304 or later)			
Defects Resolved With This Release			
Genlock issues:			
No display seen on the screen when Genlock is selected for HD-SDI input 3, 4 and 3G-SDI Output (799941)			
Cut to Black issues:			
'Cut to Black' is not working properly (800906)			
'Cut to Black' command is slow to execute and is sometimes delayed (800696)			
Communication API issues:			
Erroneous Auto Log Off's CRM64844 (800913, 800953)			
Aspect Ratio issues			
Aspect ratio and physical sizes are incorrect for Template outputs and inputs (800598)			
Resizing outputs by entering W/H values does not maintain original Aspect Ratio (800724)			
Edge blend issues:			
Edge blend issue in M302.B04L (800657)			
CORIOgrapher Edge Blending Issues (800916)			
Change Edgeblend location X causes Y to change as well (801047)			
Preset issues			
presets breaking with a CORIOmaster running 302 and CORIOgrapher (800905)			
CORIOgrapher crashes whilst recalling Presets in Dashboard (800944)			
Window configuration issues			
CORIOgrapher mini Video Wall canvas navigation showing 4 instead of 1 (800593)			
Incorrect window position after move - 'Undo' then 'Take' (800967)			
Video wall test case states "max windows" set to 8EHQ8HQ should be 32 rather than 40 (801030)			
Window configuration different in general settings to that in video wall editor (801032)			
Adding a Output that has previously been added crashes CORIOgrapher (801035)			
When an input slot has been updated to a null state and you click configure CORIOgrapher crashes. (801040)			
Out of bound Output detection does not update Orange rectangle when resizing Output (801038)			
CORIOgrapher installation issues			
Old versions of CORIOgrapher are not being removed with new installs (800974)			
Known Issues With This Release			
CORIOgrapher software can't log in over RS-232 via HDBaseT extenders (800630)			
CORIOgrapher serial connection issue (800829)			
Mixing Output Aspect Ratios on a canvas issue (800912)			
Outputs next to each other with different resolution causes overlap in canvas (800946)			
Mixing DVI and SDI outputs on the same canvas causes presets not loading until a "Take" is performed (801126)			
Supported CORIOmaster firmware			
M304_00 or later			
NOTE: CORIOgrapher will not connect to CORIOmaster firmware versions prior to M304_00			
Supported Operating Systems			
CORIOgrapher requires .NET 4.5 (Windows Vista, Windows 7 and Windows 8)			
Installation Instructions			
WARNING: You must update to CORIOmaster or CORIOmaster mini firmware version M304_00 prior to upgrading to this verion of CORIOgrapher.			
NOTE: You will need to re-enter the serial number when installing.			
Please make a note of the serial number before installing.			
Run the file Setup_X.X.X.X.exe and follow the instructions on the screen			
Points of contact			
Product Manager		R&D	
Tony McAhren		Paul Hounslow	
Tony.McAhren@tvone.com		paul.hounslow@tvone.com	